






| | | | | | | | | | | | | | | | | | | |
|---|--|-------------|-----------------|------------------|------------------|-----------------|-----|--|----|-----|-----|-------|-----|-----|-----|--------------------|-------------|----|
|  | G5P RoHS Complt | Yes | 5 35 | 4.5 21 | 3.5 14 | 2.8 8 | 500 |  SPST | P | 1.2 | 1.2 | 0.020 | 2.5 | 2.5 | 50 | 30@ 55- 2000 | 5 million | 28 |
|  | GR6 HBA318 RoHS Complt | No | 7 10 | 7 10 | 7 6 | 7 6 | - | SPST-NO | A | 0.4 | 5* | 0.050 | 2 | 1 | 100 | 20@ 10- 500 | 100 million | 24 |
|  | GR6 JNB218 RoHS Complt | No | 8 8 | 8 8 | 8 6 | 8 6 | - | SPST-NC | B | 4 | 3* | 0.050 | 3 | 2 | 100 | 20@ 10- 500 | 100 million | 5 |
|  | G12 RoHS Complt | Yes | 8 10 | 5 7 | 3 3 | 2 2 | 500 | DPDT | 2C | 0.8 | 1.5 | 0.020 | 15 | 9 | 30 | 10@ 10- 2000 | 1 million | 71 |
|  | G12L RoHS Complt | Yes | 8 10 | 5 7 | 3 3 | 2 2 | 500 |  DPDT | 2C | 0.8 | 1.5 | 0.020 | 15 | 9 | 30 | 10@ 10- 2000 | 1 million | 71 |
|  | G47A RoHS Complt | Yes | 8 12 | 7.5 10 | 7 5 | 5 3 | 500 | SPST-NO | A | 1.2 | 1.2 | 0.030 | 10 | 10 | 30 | 10@ 55- 1000 | 2 million | 26 |
|  | G47B RoHS Complt | Yes | 8 12 | 7.5 10 | 7 5 | 5 3 | 500 | SPST-NC | B | 1.2 | 1.2 | 0.030 | 10 | 10 | 30 | 10@ 55- 1000 | 2 million | 26 |
|  | G43A RoHS Complt | Yes | 10 25 | 7 20 | 6 13 | 4 10 | 500 | SPST-NO | A | 1.2 | 1.2 | 0.020 | 10 | 10 | 50 | 10@ 55- 2000 | 2 million | 28 |
|  | G43B RoHS Complt | Yes | 10 25 | 7 20 | 6 13 | 4 10 | 500 | SPST-NC | B | 1.2 | 1.2 | 0.020 | 10 | 10 | 50 | 10@ 55- 2000 | 2 million | 28 |
|  | G43C RoHS Complt | Yes | 10 25 | 7 20 | 6 13 | 4 10 | 500 | SPDT | C | 1.2 | 1.2 | 0.020 | 10 | 10 | 50 | 10@ 55- 2000 | 2 million | 28 |
|  | G8 RoHS Complt | Yes limited | 15 30 | 12 18 | 9 10 | 7 6 | 500 | SPDT | C | 0.5 | 1 | 0.025 | 15 | 9 | 50 | 10@ 55- 500 | 1 million | 85 |
|  | G8L RoHS Complt | Yes limited | 15 30 | 12 18 | 9 10 | 7 6 | 500 |  SPDT | C | 0.5 | 1 | 0.025 | 15 | 9 | 50 | 10@ 55- 500 | 1 million | 85 |
|  | G2 RoHS Complt | No | 15 50 | 12 30 | 9 17 | 7 10 | 500 | SPDT | C | 0.5 | 1 | 0.012 | 15 | 9 | 50 | 10@ 55- 500 | 1 million | 85 |

| | | | | | | | | | | | | | | | | | | |
|---|-------------------------------|----------------|-----|-----|----|----|-----|---------|----|-----|-----|-------|-----|----|----|-------------------|-----------|-----|
|  | G2L RoHS Complnt | No | 15 | 12 | 9 | 7 | 500 | SPDT | C | 0.5 | 1 | 0.012 | 15 | 9 | 50 | 10@ 55- 500 | 1 million | 85 |
| | | | 50 | 30 | 17 | 10 | | | | | | | | | | | | |
|  | G9 RoHS Complnt | Yes | 15 | 13 | 10 | - | 500 | SPDT | C | 3 | 3.5 | 0.010 | 30 | 8 | 50 | 10@ 55- 500 | 1 million | 300 |
| | | | 75 | 35 | 22 | - | | | | | | | | | | | | |
|  | G23 RoHS Complnt | Yes | 20 | 12 | 8 | 5 | 500 | DPDT | 2C | 3 | 3.5 | 0.010 | 30 | 10 | 50 | 10@ 55- 300 | 1 million | 380 |
| | | | 75 | 35 | 22 | 15 | | | | | | | | | | | | |
|  | G52 RoHS Complnt | Yes limited | 25 | 15 | 10 | 7 | 500 | SPDT | C | 5 | 5 | 0.003 | 100 | 15 | 30 | 10@ 55- 500 | 1 million | 992 |
| | | | 150 | 120 | 75 | 30 | | | | | | | | | | | | |
|  | G20 RoHS Complnt | No | 28 | 22 | 12 | 10 | 500 | SPST-NO | X | 2.5 | 2.5 | 0.005 | 18 | 10 | 30 | 10@ 55- 500 | 2 million | 342 |
| | | | 110 | 60 | 40 | 30 | | | | | | | | | | | | |

* Closed contacts to ground.

* * 30 kV at 60Hz

02/15/10



GIGAVAC® - P.O. Box 4428 - Santa Barbara, CA 93140-4428 - ph +(805) 684-8401 - +(805) 755-2000
 fx +(805) 684-8402 - - www.gigavac.com - ©Copyright 2003-2010 GIGAVAC, LLC.