














GIGAVAC RELAYS & CONTACTORS









Products are listed in ascending **voltage** order
 Click P/N for detail specifications

RELAYS & CONTACTORS FOR CONTACT MAKE ONLY APPLICATIONS

PART #	HOT SWITCH	RATED OPER VOLTAGE (KV PEAK)				COIL HI-POT (VRMS 60 HZ)	CONTACT CONFIG	FORM	CONTACT CAPAC. (PF)		MAX CONTACT RESIST. (OHMS)	MAX OPE TIME (MS)	MAX REL. TIME (MS)	SHOCK 11 MS 1/2 SINE (G'S PEAK)	VIBR. G'S PEAK @ FREQ.	MECH. LIFE (CYCLES)	WEIGHT NOM. (G)
		DC OR 60 HZ	25 MHZ	16 MHZ	32 MHZ				BETWEEN OPEN CONTACTS	OPEN CONTACTS TO GROUND							
 GX21	Yes	.75	0	0	0	2.5kV	SPST-NO Optional SPST-NO(Aux)	A A Aux	-	-	0.0004	20	12	20	15@ 500- 2000	1 million	440
		150	-	-	-												
 GX11	Yes	.75	0	0	0	2.5kV	SPST-NO Optional SPST-NO(Aux)	A A Aux	-	-	0.0004	20	12	20	15@ 500- 2000	1 million	500
		150	-	-	-												
 GX12	Yes	.75	0	0	0	2.5kV	SPST-NO Optional SPST-NO(Aux)	A A Aux	-	-	0.0004	20	12	20	15@ 500- 2000	1 million	540
		225	-	-	-												
 GX14	Yes	.75	-	-	-	2.5kV	SPST-NO Optional SPST-NO(Aux)	A A Aux	-	-	0.0004	20	12	20	15@ 500- 2000	1 million	500
		350	-	-	-												
 GX23	Yes	.75	-	-	-	2.5kV	SPST-NO Optional SPST-NO(Aux)	A A Aux	-	-	0.0004	20	12	20	15@ 500- 2000	1 million	440
		350	-	-	-												
 GXNC14	Yes	.75	-	-	-	2.5kV	SPST-NC	B or Y	-	-	0.0004	20	12	20	15@ 500- 2000	1 million	500
		350	-	-	-												
 GXL14	Yes	.75	4.5	3.5	2.8	2kV	LATCHING SPST Optional SPST (Aux)	P	-	-	0.0004	20	20	10	10@ 500- 2000	1 million	500
		350	-	-	-												
 GX16	Yes	.75	0	0	0	2kV	SPST-NO Optional SPST-NO(Aux)	A A Aux	-	-	0.0003	20	13	20	15@ 500- 2000	300K	900
		600	-	-	-												
 GH5	Make Only	3.5	-	-	-	500	SPDT	C	-	-	0.500	6	6	50	10@ 55- 2000	1 million	28
		8	-	-	-												
 GH3	Yes	3.5	-	-	-	500	SPDT	C	-	-	0.020	6	6	50	10@ 55- 2000	2 million	28
		18	-	-	-												

	G45C	Yes	5 20	4.5 16	3.5 10	2.8 8	500	SPDT	C	1.6	2	0.050	10	10	30	10@ 10- 2000	2 million	21
	G41A	Yes	5 30	4.5 24	3.5 16	2.8 12	500	SPST-NO	A	1.2	1.2	0.020	10	10	50	10@ 55- 2000	2 million	28
	G41B	Yes	5 30	4.5 24	3.5 16	2.8 12	500	SPST-NC	B	1.2	1.2	0.020	10	10	50	10@ 55- 2000	2 million	28
	G41C	Yes	5 30	4.5 24	3.5 16	2.8 12	500	SPDT	C	1.2	1.2	0.020	10	10	50	10@ 55- 2000	2 million	28
	G17	Make Only	7.5 10	- -	- -	- -	500	DPDT	2C	0.5	1	1.0	15	9	50	10@ 55- 500	1 million	140
	GH6	Make Only	8 8	- -	- -	- -	500	SPDT	C	-	-	0.500	6	6	50	10@ 55- 2000	1 million	40
	G12	Yes	8 10	5 7	3 3	2 2	500	DPDT	2C	0.8	1.5	0.020	15	9	30	10@ 10- 2000	1 million	71
	G12L	Yes	8 10	5 7	3 3	2 2	500	LATCHING DPDT	2C	0.8	1.5	0.020	15	9	30	10@ 10- 2000	1 million	71
	G47A	Yes	8 12	7.5 10	7 5	5 3	500	SPST-NO	A	1.2	1.2	0.030	10	10	30	10@ 55- 1000	2 million	26
	G47B	Yes	8 12	7.5 10	7 5	5 3	500	SPST-NC	B	1.2	1.2	0.030	10	10	30	10@ 55- 1000	2 million	26
	GH4	Yes	8 15	- -	- -	- -	500	SPDT	C	-	-	0.020	6	6	50	10@ 55- 2000	2 million	40
	GR5LTA	Yes	10 5	- -	- -	- -	-	SPST-NO	A	1	8*	0.250	2	2	100	20@ 10- 500	1 billion	28

	GR5LTB	Yes	10 5	- -	- -	- -	-	SPST-NC	B	1	8*	0.250	2	2	100	20@ 10- 500	1 billion	28
	G43A	Yes	10 25	7 20	6 13	4 10	500	SPST-NO	A	1.2	1.2	0.020	10	10	50	10@ 55- 2000	2 million	28
	G43B	Yes	10 25	7 20	6 13	4 10	500	SPST-NC	B	1.2	1.2	0.020	10	10	50	10@ 55- 2000	2 million	28
	G43C	Yes	10 25	7 20	6 13	4 10	500	SPDT	C	1.2	1.2	0.020	10	10	50	10@ 55- 2000	2 million	28
	G81A G81B	Yes	10 5, 20 or 30	- -	- -	- -	-	SPST-NO SPDT-NC	A B	- -	- -	0.030	10	10	30	10@ 55- 500	2 million	57
	G81C	Yes	10 5 or 30	- -	- -	- -	-	SPDT	C	- -	- -	0.050	10	10	30	10@ 55- 500	2 million	71
	GR5MTA	Yes	15 5	- -	- -	- -	-	SPST-NO	A	1	8*	0.250	3	2	100	20@ 10- 500	100 million	28
	G13	Make Only	15 10	- -	- -	- -	500	DPDT	2C	0.5	1	1.0	15	9	50	10@ 55- 500	1 million	142
	G13L	Make Only	15 10	- -	- -	- -	500	LATCHING DPDT	2C	0.5	1	1.0	15	9	50	10@ 55- 500	1 million	142
	G15	Make Only	15 12	- -	- -	- -	500	SPDT	C	- -	- -	1.0	15	9	50	10@ 55- 500	1 million	85
	G15L	Make Only	15 12	- -	- -	- -	500	LATCHING SPDT	C	- -	- -	1.0	15	9	50	10@ 55- 500	1 million	85
	G8	Yes limited	15 30	- 18	- 10	- 6	500	SPDT	C	0.5	1	0.025	15	9	50	10@ 55- 500	1 million	85
	G8L	Yes limited	15 30	- 18	- 10	- 6	500	LATCHING SPDT	C	0.5	1	0.025	15	9	50	10@ 55- 500	1 million	85

	G52	Yes limited	25 150	15 120	10 75	7 30	500	SPDT	C	5	5	0.003	100	15	30	10@ 55- 500	1 million	992
	G61	Make Only	35 10	- -	- -	- -	500	SPST-NO SPDT-NC SPDT	A B C	-	-	1.0	15	15	20	10@ 55- 500	1 million	336
	G61L	Make Only	35 10	- -	- -	- -	500	LATCHING SPST SPDT	A C	-	-	1.0	15	15	20	10@ 55- 500	1 million	336
	G60C	Make Only	35 12	- -	- -	- -	500	SPDT	C	-	-	1.0	15	15	50	10@ 55- 500	1 million	85
	G60L	Make Only	35 12	- -	- -	- -	500	LATCHING SPDT	C	-	-	1.0	15	15	50	10@ 55- 500	1 million	85
	G64	Make Only	50 10	- -	- -	- -	500	SPST-NO SPDT-NC SPDT	A B C	-	-	1.0	15	15	10	10@ 55- 500	1 million	340
	G64L	Make Only	50 10	- -	- -	- -	500	LATCHING SPDT	C	-	-	1.0	15	15	10	10@ 55- 500	1 million	340
	G71	Make Only	70 10	- -	- -	- -	500	SPST-NO SPDT-NC SPDT	A B C	-	-	2.0	20	15	20	10@ 55- 500	.5 million	336
	G71L	Make Only	70 10	- -	- -	- -	500	LATCHING SPST SPDT	A C	-	-	2.0	20	15	20	10@ 55- 500	.5 million	336

*Closed contacts to ground.
**30 kV at 60Hz

09/06/11



GIGAVAC® - P.O. Box 4428 - Santa Barbara, CA 93140-4428 - ph +(805) 684-8401 - +(805) 755-2000
fx +(805) 684-8402 - info@gigavac.com - www.gigavac.com - ©Copyright 2003-2011 GIGAVAC, LLC.