

JENNINGS CROSS REFERENCE














Products are listed in ascending **voltage** order
Click P/N for detail specifications




- Select Jennings P/N -














Jennings Technology high voltage relay part number cross reference to GIGAVAC part numbers















Nearly all GIGAVAC Relays and Contactors are **RoHS Fully Compliant** and are in stock








	GIGAVAC PART #	HOT SWITCH	RATED OPER VOLTAGE (KV PEAK)				COIL HI-POT (VRMS 60 HZ)	CONTACT CONFIG	FORM	CONTACT CAPAC. (PF)		MAX CONTACT RESIST. (OHMS)	MAX OPE TIME (MS)	MAX REL. TIME (MS)	SHOCK 11 MS 1/2 SINE (G'S PEAK)	VIBR. G'S PEAK @FREQ.	MECH. LIFE (CYCLES)	WEIGHT NOM. (G)
	JENNINGS PART #		MAX CONT. CURRENT (AMPS)							BETWEEN OPEN CONTACTS	OPEN CONTACTS TO GROUND							
			DC OR 60 HZ	25 MHZ	16 MHZ	32 MHZ												
	GX21	Yes	.75	-	-	-	2.5kV	SPST-NO	A	-	-	0.0004	20	12	20	15@ 500-2000	1 million	440
	x		150	-	-	-		Optional SPST-NO (Aux)	A Aux	-	-							
	GX11	Yes	.75	-	-	-	2.5kV	SPST-NO	A	-	-	0.0004	20	12	20	15@ 500-2000	1 million	500
	x		150	-	-	-		Optional SPST-NO (Aux)	A Aux	-	-							
	GX12	Yes	.75	-	-	-	2.5kV	SPST-NO	A	-	-	0.0004	20	12	20	15@ 500-2000	1 million	540
	x		225	-	-	-		Optional SPST-NO (Aux)	A Aux	-	-							
	GX14	Yes	.75	-	-	-	2.5kV	SPST-NO	A	-	-	0.0004	20	12	20	15@ 500-2000	1 million	500
	x		350	-	-	-		Optional SPST-NO (Aux)	A Aux	-	-							
	GX23	Yes	.75	-	-	-	2.5kV	SPST-NO	A	-	-	0.0004	20	12	20	15@ 500-2000	1 million	440
	x		350	-	-	-		Optional SPST-NO (Aux)	A Aux	-	-							
	GXNC14	Yes	.75	-	-	-	2.5kV	SPST-NC	B or Y	-	-	0.0004	20	12	20	15@ 500-2000	1 million	500
	x		350	-	-	-				-	-							
	GX200	Yes	.75	-	-	-	2.5kV	SPST-NO	A	-	-	0.0004	20	12	20	15@ 500-2000	1 million	440
	x		350	-	-	-		Optional SPST-NO (Aux)	A Aux	-	-							
	GXL14	Yes	.75	4.5	3.5	2.8	2kV	LATCHING SPST	P	-	-	0.0004	20	20	10	10@ 500-2000	1 million	500
			350	-	-	-		Optional SPST (Aux)										
	GX16	Yes	.75	0	0	0	2kV	SPST-NO	A	-	-	0.0003	20	13	20	15@ 500-2000	300K	900
	x		600	-	-	-		Optional SPST-NO (Aux)	A Aux	-	-							
	GR3 BJA335	No	1.5	1.5	1.5	1.5	-	SPST-NO	A	0.3	4*	0.050	0.8	0.5	100	30@ 10-2000	100 million	7
	x		3	3	3	3												

	GR6 CBA335	No	2	2	2	2	-	SPST-NO	A	0.3	6*	0.025	2	0.5	100	30@ 10- 2000	100 million	7
	x		6	6	6	6												
	GR2DNA	No	3	3	3	3	-	SPST-NO	A	1.5	6	0.100	1	1	100	30@ 10- 2000	100 million	5
	x		2	2	2	2												
	GH5	Make Only	3.5	-	-	-	500	SPDT	C	-	-	0.500	6	6	50	10@ 55- 2000	1 million	28
	x		8	-	-	-												
	GH3	Yes	3.5	-	-	-	500	SPDT	C	-	-	0.020	6	6	50	10@ 55- 2000	2 million	28
	RJ1H- 26S		18	-	-	-												
	GH1	No	3.5	2.5	2	1.5	500	SPDT	C	2	2.5	0.010	6	6	50	10@ 55- 2000	2 million	28
	RJ1A- 26S		25	14	9	7												
	GR6 FNA218	No	5	5	5	5	-	SPST-NO	A	4	3*	0.050	3	1	100	20@ 10- 500	100 million	24
	x		8	8	6	6												
	G45C	Yes	5	4.5	3.5	2.8	500	SPDT	C	1.6	2	0.050	10	10	30	10@ 10- 2000	2 million	21
	RF1D		20	16	10	8												
	G41A	Yes	5	4.5	3.5	2.8	500	SPST-NO	A	1.2	1.2	0.020	10	10	50	10@ 55- 2000	2 million	28
	RF42 RF48		30	24	16	12												
	G41B	Yes	5	4.5	3.5	2.8	500	SPST-NC	B	1.2	1.2	0.020	10	10	50	10@ 55- 2000	2 million	28
	RF41		30	24	16	12												
	G41C	Yes	5	4.5	3.5	2.8	500	SPDT	C	1.2	1.2	0.020	10	10	50	10@ 55- 2000	2 million	28
	RF61 RF64		30	24	16	12												
	GR6 HBA318	No	7	7	7	7	-	SPST-NO	A	0.4	5*	0.050	2	1	100	20@ 10- 500	100 million	24
	x		10	10	6	6												
	G17	Make Only	7.5	-	-	-	500	DPDT	2C	0.5	1	1.0	15	9	50	10@ 55- 500	1 million	140
	x		10	-	-	-												
	GR6 JNB218	No	8	8	8	8	-	SPST-NC	B	4	3*	0.050	3	2	100	20@ 10- 500	100 million	5
	x		8	8	6	6												

	GH6	Make Only	8	-	-	-	500	SPDT	C	-	-	0.500	6	6	50	10@ 55- 2000	1 million	40
	RJ1H RG1HG		8	-	-	-												
	G12	Yes	8	5	3	2	500	DPDT	2C	0.8	1.5	0.020	15	9	30	10@ 10- 2000	1 million	71
	RF7A RF7B		10	7	3	2												
	G12L	Yes	8	5	3	2	500	LATCHING DPDT	2C	0.8	1.5	0.020	15	9	30	10@ 10- 2000	1 million	71
	x		10	7	3	2												
	G47A	Yes	8	7.5	7	5	500	SPST-NO	A	1.2	1.2	0.030	10	10	30	10@ 55- 1000	2 million	26
	RF6A RF6C RF6D		12	10	5	3												
	G47B	Yes	8	7.5	7	5	500	SPST-NC	B	1.2	1.2	0.030	10	10	30	10@ 55- 1000	2 million	26
	RF5A RF5C RF5D		12	10	5	3												
	GH4	Yes	8	-	-	-	500	SPDT	C	-	-	0.020	6	6	50	10@ 55- 2000	2 million	40
	RJ1H		15	-	-	-												
	GH2	No	8	-	-	-	500	SPDT	C	-	-	0.010	6	6	50	10@ 55- 2000	2 million	40
	RJ1A RJ1A- 26N969		25	-	-	-												
	GR5LTA	Yes	10	-	-	-	-	SPST-NO	A	1	8*	0.250	2	2	100	20@ 10- 500	1 billion	28
	x		5	-	-	-												
	GR5LTB	Yes	10	-	-	-	-	SPST-NC	B	1	8*	0.250	2	2	100	20@ 10- 500	1 billion	28
	x		5	-	-	-												
	G43A	Yes	10	7	6	4	500	SPST-NO	A	1.2	1.2	0.020	10	10	50	10@ 55- 2000	2 million	28
	RF51 RF53		25	20	13	10												
	G43B	Yes	10	7	6	4	500	SPST-NC	B	1.2	1.2	0.020	10	10	50	10@ 55- 2000	2 million	28
	RF50 RF4A		25	20	13	10												
	G43C	Yes	10	7	6	4	500	SPDT	C	1.2	1.2	0.020	10	10	50	10@ 55- 2000	2 million	28
	RF62 RF3D		25	20	13	10												
	G81A G81B	Yes	10	-	-	-	-	SPST-NO SPST-NC	A B	-	-	0.030	10	10	30	10@ 55- 500	2 million	57
	x		5, 20 or 30	-	-	-												

	G81C	Yes	10	-	-	-	-	SPDT	C	-	-	0.050	10	10	30	10@ 55- 500	2 million	71
	x		5 or 30	-	-	-												
	GR5MTA	Yes	15	-	-	-	-	SPST-NO	A	1	8*	0.250	3	2	100	20@ 10- 500	100 million	28
	x		5	-	-	-												
	G13	Make Only	15	-	-	-	500	DPDT	2C	0.5	1	1.0	15	9	50	10@ 55- 500	1 million	142
	x		10	-	-	-												
	G13L	Make Only	15	-	-	-	500	LATCHING DPDT	2C	0.5	1	1.0	15	9	50	10@ 55- 500	1 million	142
	x		10	-	-	-												
	G15	Make Only	15	-	-	-	500	SPDT	C	-	-	1.0	15	9	50	10@ 55- 500	1 million	85
	x		12	-	-	-												
	G15L	Make Only	15	-	-	-	500	LATCHING SPDT	C	-	-	1.0	15	9	50	10@ 55- 500	1 million	85
	x		12	-	-	-												
	G8	Yes limited	15	12	9	7	500	SPDT	C	0.5	1	0.025	15	9	50	10@ 55- 500	1 million	85
	RB1E RB1J RD5A RD5B RD6A RD6B RJ5A		30	18	10	6												
	G8L	Yes limited	15	12	9	7	500	LATCHING SPDT	C	0.5	1	0.025	15	9	50	10@ 55- 500	1 million	85
	x		30	18	10	6												
	G18	Yes	15	-	-	-	500	SPDT	C	0.5	1	0.025	15	9	50	10@ 55- 500	1 million	85
	x		30	-	-	-												
	G2	No	15	12	9	7	500	SPDT	C	0.5	1	0.012	15	9	50	10@ 55- 500	1 million	85
	RJ4B RJ4C RJ2B RF2C RJ6B		50	30	17	10												
	G2L	No	15	12	9	7	500	LATCHING SPDT	C	0.5	1	0.012	15	9	50	10@ 55- 500	1 million	85
	x		50	30	17	10												
	G9	Yes	15	13	10	-	500	SPDT	C	3	3.5	0.010	30	8	50	10@ 55- 500	1 million	300
	x		75	35	22	-												
	G2SPD	Yes	15	12	9	7	500	DPDT	2C	1	2.5	0.012	20	8	1.5	10@ 55- 2000	1 million	160
	x		50	30	17.5	10												

	G8SPD	Yes	15	12	9	7	500	DPDT	2C	1	2.5	0.025	20	8	1.5	10@ 55- 2000	1 million	160
	x		30	18	10	6												
	G15SPD	Yes	15	-	-	-	500	DPDT	2C	-	-	0.025	20	8	1.5	10@ 55- 2000	1 million	160
	x		12	-	-	-												
	G23	Yes	20	12	8	5	500	DPDT	2C	3	3.5	0.010	30	10	50	10@ 55- 300	1 million	380
	x		75	35	22	15												
	G38	Make Only	25	-	-	-	500	SPST-NC	Y	-	-	1.0	18	20	30	10@ 55- 500	2 million	342
	x		15	-	-	-												
	G25	Yes	25	-	-	-	500	SPDT	C	-	-	0.1	15	15	20	10@ 55- 500	1 million	320
	RB1D		18	-	-	-												
	G62	Yes	25	-	-	-	500	SPST-NO SPDT-NC SPDT	A B C	-	-	0.500	15	15	20	10@ 55- 500	1 million	340
	x		18	-	-	-												
	G62L	Yes	25	-	-	-	500	LATCHING SPST SPDT	A C	-	-	0.500	15	15	20	10@ 55- 500	1 million	340
	x		18	-	-	-												
	G28	Make Only	25	-	-	-	500	SPST-NO	X	-	-	1.0	18	10	30	10@ 55- 500	2 million	342
	x		30	-	-	-												
	G32	Yes	25	-	-	-	500	SPST-NC	Y	2.5	2.5	0.01	18	20	30	10@ 55- 500	2 million	342
	RS10 RJ10H		45	-	-	-												
	G22	Yes	25	-	-	-	500	SPST-NO	X	2.5	2.5	0.005	18	10	30	10@ 55- 500	2 million	342
	x		65	-	-	-												
	G50	Yes	25	-	-	-	500	SPDT	C	5	5	0.005	100	15	30	10@ 55- 500	1 million	992
	RJ8H		110	-	-	-												
	G52	Yes limited	25	15	10	7	500	SPDT	C	5	5	0.003	100	15	30	10@ 55- 500	1 million	92
	RJ8A		150	120	75	30												
	G20	No	28	22	12	10	500	SPST-NO	X	2.5	2.5	0.005	18	10	30	10@ 55- 500	2 million	342
	RJ8A		110	60	40	30												
	G61	Make Only	35	-	-	-	500	SPST-NO SPDT-NC SPDT	A B C	-	-	1.0	15	15	20	10@ 55- 500	1 million	336
	x		10	-	-	-												

	G61L	Make Only	35	-	-	-	500	LATCHING SPST SPDT	A C	-	-	1.0	15	15	20	10@ 55- 500	1 million	336
	x		10	-	-	-												
	G60C	Make Only	35	-	-	-	500	SPDT	C	-	-	1.0	15	15	50	10@ 55- 500	1 million	85
	x		12	-	-	-												
	G60L	Make Only	35	-	-	-	500	LATCHING SPDT	C	-	-	1.0	15	15	50	10@ 55- 500	1 million	85
	x		12	-	-	-												
	G64	Make Only	50	-	-	-	500	SPST-NO SPDT-NC SPDT	A B C	-	-	1.0	15	15	10	10@ 55- 500	1 million	340
	RGH5		10	-	-	-												
	G64L	Make Only	50	-	-	-	500	LATCHING SPDT	C	-	-	1.0	15	15	10	10@ 55- 500	1 million	340
	x		10	-	-	-												
	G71	Make Only	70 ***	-	-	-	500	SPST-NO SPDT-NC SPDT	A B C	-	-	2.0	20	15	20	10@ 55- 500	.5 million	336
	RGH3		10	-	-	-												
	G71L	Make Only	70 ***	-	-	-	500	LATCHING SPST SPDT	A C	-	-	2.0	20	15	20	10@ 55- 500	.5 million	336
	x		10	-	-	-												

*Closed contacts to ground.

***30 kV at 60Hz

04/22/11



GIGAVAC® - P.O. Box 4428 - Santa Barbara, CA 93140-4428 - ph +(805) 684-8401 - +(805) 755-2000
 fx +(805) 684-8402 - info@gigavac.com - www.gigavac.com - ©Copyright 2003-2011 GIGAVAC, LLC.