

	<b>G61L</b>	Make Only	35	-	-	-	500	LATCHING SPST SPDT	A C	-	-	1.0	15	15	20	10@ 55- 500	1 million	340
			10	-	-	-												
	<b>G64L</b>	Make Only	50	-	-	-	500	LATCHING SPDT	C	-	-	1.0	15	15	10	10@ 55- 500	1 million	340
			10	-	-	-												
	<b>G71L</b>	Make Only	70	-	-	-	500	LATCHING SPST SPDT	A C	-	-	2.0	20	15	20	10@ 55- 500	.5 million	510
			10	-	-	-												

\*Closed contacts to ground.

\*\*30 kV at 60Hz

01/11/11



GIGAVAC® - P.O. Box 4428 - Santa Barbara, CA 93140-4428 - ph +(805) 684-8401 - +(805) 755-2000  
 fx +(805) 684-8402 - [info@gigavac.com](mailto:info@gigavac.com) - [www.gigavac.com](http://www.gigavac.com) - ©Copyright 2003-2011 GIGAVAC, LLC.